

# HP0-725

## HP

### *Enterprise Integration and Management of HP ProLiant Servers*

Visit: <http://www.pass4sureofficial.com/exams.asp?examcode=HP0-725>

Pass4sureofficial.com is a reputable IT certification examination guide, study guides and audio exam provider, we not only ensure that you pass your HP0-725 exam in first attempt, but also you can get a high score to acquire HP certification.

If you use pass4sureofficial HP0-725 Certification questions and answers, you will experience actual HP0-725 exam questions/answers. We know exactly what is needed and have all the exam preparation material required to pass the exam. Our HP exam prep covers over 95% of the questions and answers that may be appeared in your HP0-725 exam. Every point from pass4sure HP0-725 PDF, HP0-725 review will help you take HP HP0-725 exam much easier and become HP certified. All the Questions/Answers are taken from real exams.

Here's what you can expect from the Pass4sureOfficial HP HP0-725 course:

- \* Up-to-Date HP HP0-725 questions taken from the real exam.
- \* 100% correct HP HP0-725 answers you simply can't find in other HP0-725 courses.
- \* All of our tests are easy to download. Your file will be saved as a HP0-725 PDF.
- \* HP HP0-725 brain dump free content featuring the real HP0-725 test questions.

HP HP0-725 certification exam is of core importance both in your Professional life and HP certification path. With HP certification you can get a good job easily in the market and get on your path for success. Professionals who passed HP HP0-725 exam training are an absolute favorite in the industry. You will pass HP HP0-725 certification test and career opportunities will be open for you.



**QUESTION: 1**

A customer wants to verify the performance gain of Intel Hyper-Threading technology on an enterprise by disabling Hyper-Threading technology. Which utility will be enable the customer to accomplish his task?

- A. Array Configuration Utility (ACU)
- B. ROM-Based Setup Utility (RBSU)
- C. ROMpaq Utility
- D. System Configuration Utility (SCU)

**Answer: B**

**QUESTION: 2**

Which technology enables a single hard drive on a SCSI bus to accept multiple commands for execution?

- A. Tagged Command Queueing
- B. Queued SCSI bus reset
- C. Quick Connect/Quick Disconnect
- D. LIP isolation

**Answer: A**

**QUESTION: 3**

A customer has installed 6GB of memory in an HP ProLiant server running Windows 2000 Advanced Server, but the operating system sees only 4GB of memory. How should the customer correct this problem?

- A. Reinstall the memory.
- B. Add the /6GB switch to the boot.ini file.
- C. Add the /PAE switch to the boot.ini file.
- D. Add the /AWE switch to the boot.ini file.

**Answer: C**

**QUESTION: 4**

An HP PCI device in a hot-plug slot was disabled using the Device Manager on an HP ProLiant DL 580 server running Microsoft Windows Server 2003. After the device was disabled, the green LED started blinking. What should be done to correct the issue?

- A. Replace the PCI device.
- B. Install a hot-plug PCI compliant card.
- C. Replace the I/O board.
- D. Disable the slot with the hot-plug utility.

**Answer:** D

**QUESTION: 5**

You need upgrade the hot-pluggable memory in an HP ProLiant server without shutting down the server. It is safe to remove hot-pluggable memory when the hot-plug LED is in what state?

- A. amber
- B. no longer illuminated
- C. red
- D. green

**Answer:** D

**QUESTION: 6**

What is the advantage of double data (DDR) memory?

- A. The clock speed of the memory is twice that of the standard memory.
- B. Data is transferred on both the rising edge and the falling edge of the clock cycles.
- C. The data rate on the memory subsystem is doubled by interleaving this type of memory.
- D. Uses a memory bus that is twice as wide as standard memory.

**Answer:** B

**QUESTION: 7**

A customer is running Windows Server 2003 on an HP ProLiant server. The server has four Intel Xeon- MP processors with 512KB of L2 4GB of RAM, and dual 10/100/1000 Ethernet controllers. This server is running as an online transaction processing database server for the

web-based storefront. The customers are complaining about slow transactions. What is the recommended course of action?

- A. Install an SSL encryption card on the server.
- B. Install an additional 1GB of RAM.
- C. Install an additional 10/100/1000 Ethernet controller.
- D. Replace the existing processors with 2MB with cache versions.

**Answer:** D

**QUESTION: 8**


When proposing a new HP ProLiant server for an enterprise-class customer, which bus type gives the best performance for high-bandwidth devices such as Gigabit Ethernet controllers?

- A. PCI-X
- B. PCI
- C. EISA
- D. SCSI

**Answer:** A

**QUESTION: 9**

Exhibit



The installed Version of the HP Management Agents is more current than the Support Packs version or the latest version displayed. How can the Version Control Agents be updated to show the latest revision?

- A. Click the options button, clear the Clear Installation Log option, and restart the Management Agent.
- B. Go to the root of the Web Management interface, select the Version Control Repository Manager (VCRM), click the Options link, and select rescan.
- C. Click the Options button and use the pulldown menu for Reference Support Pack to select the current version.
- D. Go to the root of the Web Manager interface, select the VCRM, click the Catalog link, and the select the correct Manager Suite under the correct Operating System section.

**Answer: C**

**QUESTION: 10**

When connecting a 1Gb/s FCA to a 2Gb/s SAN switch, what type of fibre cable connectors are required?

- A. LC -> LC
- B. SC -> SC
- C. SC -> LC
- D. SC -> MTRJ

**Answer: C**

**QUESTION: 11**

New installation of 250 Remote Insight Lights Out Edition II (RILOE II) boards with the default configuration have been added to a customer's data center. From consoles in the data center, SSL login is successful. From remote locations, the console cannot be logged in to. What is the most likely cause?

- A. Port 23 is blocked on the routers.
- B. Port 443 is blocked on the routers.
- C. Certificate security has not been enabled across the routers.
- D. A user other than an Administrator has not been set up on the RILOE II.

## Pass4SureOfficial.com Lifetime Membership Features;

- Pass4SureOfficial Lifetime Membership Package includes over **2500** Exams.
- **All** exams Questions and Answers are included in package.
- **All** Audio Guides are included **free** in package.
- **All** Study Guides are included **free** in package.
- **Lifetime** login access.
- Unlimited download, no account expiry, no hidden charges, just one time \$99 payment.
- **Free updates** for Lifetime.
- **Free Download Access** to All new exams added in future.
- Accurate answers with explanations (If applicable).
- Verified answers researched by industry experts.
- Study Material **updated** on regular basis.
- Questions, Answers and Study Guides are downloadable in **PDF** format.
- Audio Exams are downloadable in **MP3** format.
- **No authorization** code required to open exam.
- **Portable** anywhere.
- 100% success **Guarantee**.
- **Fast**, helpful support 24x7.

View list of All exams (Q&A) downloads

<http://www.pass4sureofficial.com/allexams.asp>

View list of All Study Guides (SG) downloads

<http://www.pass4sureofficial.com/study-guides.asp>

View list of All Audio Exams (AE) downloads

<http://www.pass4sureofficial.com/audio-exams.asp>

Download All Exams Samples

<http://www.pass4sureofficial.com/samples.asp>

To purchase \$99 Lifetime Full Access Membership click here

<http://www.pass4sureofficial.com/purchase.asp>

3COM	CompTIA	Filemaker	IBM	LPI	OMG	Sun
ADOBE	ComputerAssociates	Fortinet	IISFA	McAfee	Oracle	Sybase
APC	CWNP	Foundry	Intel	McData	PMI	Symantec
Apple	DELL	Fujitsu	ISACA	Microsoft	Polycom	TeraData
BEA	ECCouncil	GuidanceSoftware	ISC2	Mile2	RedHat	TIA
BICSI	EMC	HDI	ISEB	NetworkAppliance	Sair	Tibco
CheckPoint	Enterasys	Hitachi	ISM	Network-General	SASInstitute	TruSecure
Cisco	ExamExpress	HP	Juniper	Nokia	SCP	Veritas
Citrix	Exin	Huawei	Legato	Nortel	See-Beyond	Vmware
CIW	ExtremeNetworks	Hyperion	Lotus	Novell	SNIA	

